



1/24




FIG. 1

The block diagram of the sensor self-test system.






FIG. 2

Generic amplifier self-test configuration.

2/24



3/24




FIG.5

Three wire voltage mode self-test circuit.

4/24




FIG.6

Three wire charge amplifier.

5/24




FIG.7

The two-wire charge mode preamplifier with self-test feature.

6/24

140




FIG.8

7/24

142




FIG.9

8/24

144

Charge Amp configuration—calibration output voltage—
unit magnitude white noise input




FIG.10

9/24

152

Charge Amp configuration—calibration output voltage—
unit magnitude white noise input




FIG.11

10/24

154


Charge Amp configuration—calibration output voltage—
unit magnitude white noise input

FIG.12




FIG.13

11/24




FIG.14

12/24




FIG.15

13/24




FIG.16

14/24




FIG.17

15/24




FIG.18

16/24




FIG.19A




FIG.19B

17/24




FIG.20A
.5 volt excitation




FIG.20B
5 volt excitation

18/24




FIG.21A




FIG.21B

19/24




FIG.22A




FIG.22B

20/24




FIG.23

21/24




FIG.24

22/24




FIG.25A




FIG.25B

23/24




FIG.26

24/24




FIG.27

Sensor Self-Test Procedure